20 September 1965

Dear Customer

STATINTL

Enclosed you will find prints of the layout of the micrometer stage for light table # 2. The unit will meet all of your requirements as far as stereoscope position, working distance and accuracy requirements. The unit will not fit within the envelope specified for light table # 2 due to its length in the Y-Y direction. An overhang of 31/4" exists at the rear of table # 2 and 21/4" will exist at the rear of table # 3. This overhang cannot be eliminated as it would require moving the rear X-X precision way. This modification would degrade the accuracy of the entire motion in both X and Y.

STATINTL

Will you please examine the drawing and tell us if this overhang is permissible. We would like to have an answer as soon as possible as the extablishment of a delivery date for light tables # 2 and # 3 is predicated upon your decision.


Thank you very much for your assistance in this matter.


STATINTL STATINTL


Sincerely


RLG/mkr

DECLASS REVIEW BY NIMA / DoD













Approved For Release 2001/07/12 : CIA-RDP78B04747A001400030039-2









Approved For Release 2001/07/12 : CIA-RDP78B04747A001400030039-2 STATINTL

